

Aero Design Ltd.

Work Order Control Sheet

Work Order#: 2017-75 Date Opened: 26 April 17 Title: Assembly

Aircraft OEM: Bell Aircraft Model: 206L/407 Product Type: Cargo Basket Product Model: Low Ski Quantity: 1

Work Order Contents

	Initial or N/A
Work Order/Build Sheets (Procedures Provided)	N/A
Additional Work Sheets (Standard Practice)	N/A
Drawings (See List Below)	N/A
Parts Distribution Sheet	N/A
Sub Component Tags	N/A
Completed Certification (Original)	N/A
Time Sheet (R&D)	N/A
Notes	N/A

Build Sheet Contents

	Initial or N/A
Tasks Initialled	N/A
Dual Inspections Initialled	N/A

Drawing List

Drawing #	Rev #	Description	Initial or N/A

Traveller

Initial or N/A

Component Completion

	As Instructed
Quantity Complete on This Work Order	1
Quantity Incomplete on This Work Order	N/A
Further Processing Required Before Release	N/A
Release to Stock as Components	N/A

Certification

	Initial or N/A
Form One Completed	N/A
Serviceable (Green) Tag Completed	N/A
In Process (Yellow) Tag Completed	N/A
Unserviceable (Red) Tag Completed	N/A
Parts Placed in Stores for Distribution	N/A

Additional Documentation

	Initial or N/A
Documentation of a minor change	N/A
Non-Conformance Report Required	N/A
Service Difficulty Report Required	N/A

Billing

	Initial or N/A
Local (Aero Design)	JC
Research and Development	N/A
Third Party	N/A

Notes:

Basket 94610-01 (S/N 94601-02) dis-assembled and media blasted prior to fresh powder coat IAW standard practices.

Basket lid 94012-01 BER, destroyed.

Work performed by:

Print: J. Rekve

Sign: *J. Rekve*

SCA: AD01

Date: 25-Jun-17

ICC / Dual Inspection preformed by:

Print: N/A

Sign: *[Signature]*

SCA:

Date:

Work Order closed by:

Print: J. Clarke

Sign: *J. Clarke*

SCA: AD02

Date: 13-Jul-17

Approved Manufacturing Facility 73-04

Form 20.0.03

Rev. Original 23 Sep 2014

BLACKCOMB HELICOPTERS LP.

AMO 133-95

1850 AIRPORT RD, PEMBERTON, BC, CANADA, V0N 2L0

NOMENCLATURE: Cargo basketPART NO.: _____ MAKE: Aeo Designs.SERIAL NO.: 94601-02REMOVAL REASON: Hole in front of basket☐ TO BE OVERHAULED☒ TO BE REPAIRED☐ TO BE SCRAPPEDTOTAL TIME: UKN TIME SINCE OVERHAUL: N/AWORK REPORT: N/AAIRCRAFT REMOVED FROM: C-FCPH A/F HOURS: 4793.526 Apr 2017 DS

DATE

INSPECTOR'S SIGNATURE

UNSERVICEABLE



Aero Design Ltd.

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Nomenclature: Lid Prop Assembly

Manufacturer: _____

Part No.: 36280-01 Serial / Batch No.: NSN

TTSN: UK TSO: NA Rem.: NA

Removed From: NA

Reason For Removal: Stiff, Hole worn out

A/C Hours at Removal: NA WO.# NA

Signature: Hammer

Date: June 28 2017 Lic. No. / SCA _____

Unserviceable



Aero Design Ltd.

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Unserviceable

Remarks

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Nomenclature: 2017/407 Low Ski No. of pieces: 1
Manufacturer: Aero Design
Part No.: 74010-01 Serial/Batch No.:
TTSN: W/K TSO: N/A Rem.: N/A
Work Order No.: 2017-75 / 2017-115
Remaining Tasks to be Performed:

Signature: Chaz Rehn ND
Date: 11 July 17 Lic. No. / SCA 73-04
Form# 20.E.02 01 Rev. 1 24 April 2014

Serviceable

Aero Design Ltd.

9888 A Malaspina Rd. Powell River, BC, V8A 0G3

Phone: 604-483-2376 Fax: 604-483-2372 E-mail: info@aerodesign.ca

AMF 73-04

Serviceable
Remarks
Basket disassembled, pre-coated and
reassembled.